

BLESSED TRINITY BUILDING COMMITTEE PROJECT COMPLETION REPORT AS OF JULY 31, 2025

New work completed in this month is listed in Bold font

Building	Project	Description
		Contractor cut out damaged area, poured new base, replaced front step and face pieces, cut out
	Church front steps repair of	damage to top landing and installed brown granite inlay, repointed joints and repaired sections of
St. Anne Church	heaved area	sidewalk, acid wash and power wash steps, installed railing
		Maintenance staff and summer hire insulated water piping above suspended ceiling, painted
St. Anne Church	Lower level ceiling repair	stained ceiling tiles.
St. Anne Church	Parish center stove replacement	Purchased and installed new commercial stove in the kitchen of the parish center
	Engineering sizing for air	Engineer hired to perform engineering calculations to size air conditioning for all spaces at St.
St. Anne Church	conditioning installation	Anne's
St. Anne Church	Exterior masonry clean and seal	Contractor power washed and sealed exterior masonry to prevent water intrusion
		Existing controls were antiquated and difficult to operate. Contractor rewired boiler zone
	Replacement of failing heating	controller, added zone control, installed RIB relays to allow system to communicate with boiler
St. Anne Church	controls	zones, installed (3) Wi-Fi thermostats.
St. Anne Church	Paint Exterior Trim	Repainted all wood trim on exterior walls by part time painter/carpenter
St. Anne Church	Church office front stairs repair	Contractor demolished shattered bluestone stairs and slabs, poured new concrete stairs.
St. Anne Church	Cast iron drain pipe repair	Contractor replace section of sewer line in basement that had several leaks in it.
St. Anne Church	Chapel entrance stair repair	Contractor repaired crumbling Chapel entrance stairs.
St. Anne Church	Parking lot curb repair	Contractor replaced damaged asphalt curbing along driveway
St. Anne Church	Chapel ceiling water damage	Roberto repaired and repainted spline ceiling tiles
	Replace water damaged carpet in	Via an anonymous donation Water damaged carpet in basement under rectory connector and
St. Anne Church	basement under rectory	large classroom replaced
St. Anne Church	Crying Room Ceiling Repair	Roberto repaird and repainted spline ceiling tiles
St. Anne Church	New Exterior Front Doors	Front Doors were replaced with new storefront system
		Reconstructed aprons at St. Anne.
St. Anne Church		Reconstructed parking lot at rectory side at lot at(St. Catherines.
St. Catherine Church		Removed and treated weeds in cracks, filled cracks with crack sealer, sealcoated, striped parking
St. Catherine Rectory	Parking lot repair	and gore lines and pavement markings at both churches.
St. Anne Church		
St. Catherine Church		Asbestos testing performed throughout St. Anne and St. Catherine buildings to identify hazard for
St. Catherine Rectory	Test for presence of asbestos	upcoming work.

		Contractor replaced the roof in FY2023. The work was funded by a loan from the diocese. The
St. Catherine Church	Roof replacement	capital campaign paid off the balance on the loan.
		One HVAC unit in Parish Center failed completely in FY2022. Contractor replaced the unit in kind.
		The capital campaign paid back the Finance Committee who funded from the parish
St. Catherine Church	Parish Center HVAC replacement	appropriations in FY 2022
		Four HVAC units at St. Catherines were close to failing completely; parts for repairs were no
St. Catherine Church	HVAC system replacement	longer readily available. Contractor replaced in size and kind the four HVAC units.
	Installation of missing service	
	sink; there was not a service sink	Contractor installed a 24"x24" service sink in basement, ran water lines from existing lines to
St. Catherine Church	in the church or parish center	sink, connect new sink to existing sewage ejector drain and vent.
		Contractor repaired failing concrete caps, power-washed exterior, repointed all building block,
St. Catherine Church	Exterior masonry repair	and sealed exterior masonry to alleviate water intrusion.
	Parish center deck repainting and	Part time painter/carpenter and maintenance staff Installed new footing, reconstructed stairs and
St. Catherine Church	repair of failing steps and footing	railings. Deck restained by Mission Trip students
St. Catherine Church	Exterior gutter repair	Maintenance staff repaired exterior gutters.
	Repair rubber roof at the church	
St. Catherine Church	entrance vestibule	Contractor repaired the rubber roof that was leaking
	Repair water damaged and	Part time painter carpenter removed mildew, repaired water damaged drywall, prepared and
St. Catherine Church	mildewed basement stairs	painted the basement stairwell.
	Mezzanine truss	Truss esdeemed structurally sound, only cracks. Part time painter/carpenter caulked and painted
St. Catherine Church	assessment/repair	trusses in the parish center mezzanine.
	Parish center repair leaking	
St. Catherine Church	windows	Part time painter/carpenter caulked windows in the parish center that were leaking.
		Existing railings were too far from the church doors to be functional. New decorative railings were
	Install new railings at Church	added at the Church main entrance on outside steps to be functional for all masses and
St. Catherine Church	entrance	functional for funerals.
	Baptismal font restoration and	Contractor repaired and restored baptismal font by filling pitting with epoxy, remove calcium
St. Catherine Church	repair	buildup, buffing and sealing.
		Door difficult to operate and lock: Volunteers and maintenance staff replaced staff entrance
St. Catherine Church	Staff entrance door replacement	steel door on the rectory side.
St Catherine Church	Repair Parish Center Deck	Roberto repaired structural damage and replaced stairs

St. Catherine Rectory	Installation of Exterior Insulation	Building was fully insulated via MassSave contractorparish paid only 30% of the cost
St. Catherine Rectory	Kitchen flooring	Kitchen flooring was worn and tornreplaced with new composite flooring via donation
St. Catherine Rectory	Repair of knob and tube wiring	Installed new electrical service with code complaint meter and service connection; replaced knob and tube circuits with code compliant wiring. Roberto completed repair of holes in walls and ceiling required to install new wiring.
St. Catherine Rectory	Rectory sunroom roof replacement	Rectory sunroom roof was leaking into the occupied space. Contractor stripped multiple layers of roofing, remove rotted roof sheathing, installed new sheathing, underlayment and .060 EPDM rubber roofing including waster removal.
St. Catherine Rectory	Deck was in disrepair	Mission trip students restained the deck.
St. Catherine Rectory	Second floor repairs	Strip wallpaper, repair drywall/plaster, prep, paint second floor sitting room.
St. Catherine Rectory	First floor bathroom repair	Replace flooring, scrape and paint walls.
St. Catherine Rectory	Sunroom furniture replacement	Sunroom furniture was old and delipidated. Replaced sofa, three recliners, rug and table.
St. Catherine Rectory	doors	throughout the building. He also did additional repairs in the kitchen
St Catherine Church	Refinish of Parish Center Floor Repair holes in walls and repair	Parish center wood flooring was worn; refinished both main space and stage Part time painter/carpenter patched and repaired walls, painted walls and filled in to repair doors
St Catherine Church	Exterior Light Post Replacement	Several light posts alone North Main St were hit and knocked over; replacedall and salvage good parts to keep them consistent along the street partially insurance claim.
St Catherine Church	Bathroom Tile Repairs	Roberto completed tile replacement
St Catherine Church	Bathroom Repairs and Maintenance	Roberto completed needed repairs and maintenance, regrouting etc.
St Catherine Church	Painting Parish Hall	Roberto completed painting in some worn areas of the parish hall
St Catherine Church	Insulated Fire Suppression piping Closet	Roberto insulated and repaired closet walls to prevent fire suppression piping from freezing.
St Catherine Church	Repair Walls Entryway	Roberto completed these repairs