




Project Overview and Details


This photo report is for Saint Catherine of Alexandria, Westford, Massachusetts. Primary concern is the roof and drainage. There has been water penetration to the interior of the building.


A secondary concern would be masonry maintenance as noted in photos below.

Both the roof and masonry building components may be contributing factors in the appearance of a black substance on the ceiling and gable walls of the church. Identification of this substance wasn't possible from grade. Not photos below.





Project Photos















Page - 4
Powered by **fastfield**







Page - 5
Powered by **fastfield**








Page - 6
Powered by **fastfield**

































































































































































































































Project Video